



・材料




・試験方法




・試験片
(厚さ B=3mm)





・試験温度




・負荷荷重レベル




・破断サイクル
(190266)






(a) 破壊起点近傍

500 μm




(b) 拡大

50 μm



(c) 拡大

20 μm



(d) 拡大

5 μm